

Oil Field Environmental Incident Summary

Incident: 20150127083912 **Date/Time of Notice:** 01/27/2015 08:39

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: BELLE SWD 5503 43-1

Field Name: SQUIRES

Well File #: 90147

Date Incident: 1/26/2015 **Time Incident:** 13:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 103

Sec: 1

Qtr: SW SE

Location Description: A mist of oil got into the field to the east of location. It is approximately 40 feet Wide by 150 feet long.

Submitted By: John M. Jochim

Received By:

Contact Person: John M. Jochim
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	490	Barrels	487	Barrels	487	barrels
Brine	455	Barrels	454	Barrels	454	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/28/2016

Clean Up Concluded: 1/29/2015

Risk Evaluation:

none

Areal Extent:

The extent off location is approximately 40 feet wide by 150 feet long.

Potential Environmental Impacts:

none

Action Taken or Planned:

Replace High High with a different model of float.

Wastes Disposal Location: On site

Agencies Involved:

Updates

Date: 1/27/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 1/29/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/29/2015 at 13:30, on location. Spray visible to the southeast on to a tilled field, extending from the tank battery to the telephone poles along 59th Street, a distance of more than 500 feet. Area reported as impacted appears to be underestimated. Frozen over water in ditch of 59th Street. Electrical conductivity readings taken to ascertain any salt impact with the oil. Ditch water ~300 uS. Soil reading in field: 3"= ~800 uS, 6"=~1000 uS. Called report contact twice but got busy signal both times. Will call again later today.

Date: 2/4/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call with report contact. Amendment being applied to impacted soil. Landowner has been notified and agrees with methods being used.

Date: 4/26/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 10:44, 4/26/2016.

No signs of impacts at the time of inspection.

Follow up with company regarding sampling and closure.